

April 2015



Professional Control and Monitor GUI Software for Universal Switching Coporation Products Version 4.0.2

Control & Monitor Software

ROUTEWARE

Update 4.0.2

(April 08-2015)

- Crosspoint Display now reflects changes in port names when they happen
- Over-redundant queries were refactored out making the crosspoint display more responsive
- Abort and Run buttons removed from Configure a New Panel Window
- Copyright date updated
- Now built under LabVIEW[™] 2014 Service Pack 1
- Crosspoint Display not updating regression fixed
- Battery test enabled
- Connections tab labels the columns correctly on fan-in
- Tool tips on LSI and NetID fixed
- Fixed toggle-on-click on Status tab LEDs
- S/N Display interprets CPU by MAC
- Properly handles a bad output on the Commands tab
- Fixed problem with Crosspoint Display not updating
- Will not have issues if it encounters a module like the G2R16-3443 or -4442
- Fixed text on Settings tab under XP
- Changed Lock Code control behavior
- Changed Sort toggle in Log Viewer
- Reordering of list boxes on Commands tab
- Captions on Connections tab
- New Panel scrollbar appearance in Windows 7

iteWarePRO 4.0 2015-04